MITRATECH

TeamConnect[®] Enterprise 6.3.5 Patch 26 Release Notes

TeamConnect® Enterprise 6.3.5 Patch 26 (PTC6350026) resolves the following issue:

Issue: Intermittent Login Failures in clustered environment.

Tracking Code: SUPPORTPRI-67644

Case Number: 2023-0120-7629889

Reported Version: TCE 6.3.5

Workaround None.

Pre-Requisites

- Clustered environment.
- Automated testing script for login.

Steps to Reproduce

- Run the automated login scripts.
 - Login to the UAT environment with SSO.

Expected Results of Steps

The user should be able to login without any issues.

Actual Results of Steps

The user is facing a system error.

Root Cause Analysis

Concurrent update of login details.

MITRATECH

INSTALLATION

Important: Stop your TeamConnect® instance before updating any files in the TeamConnect® war file.

1. Update database and version information

Use the following steps to update the database and add patch version information to the **About** page of the **Admin Settings**.

- 1. Stop the TeamConnect® instance if it is currently running.
- 2. Backup your TeamConnect® database.
- 3. Run the script, located in \update, that is appropriate for your database server:
 - MSSQL_TeamConnect_635_Patch26.sql
 - ORACLE_TeamConnect_635_Patch26.sql
- 4. Restart TeamConnect®.

UPGRADE CONSIDERATION

No significant upgrade considerations for this patch.

LEVEL OF RISK TO UPDATE WITH PATCH

LOW